

Manhole_ID	Incomplete_Code	Field Comments	Field Comments
S09A1_002MH	DNE	DOES NOT EXIST	DOES NOT EXIST - CREW SENT OUT TO VERIFY EXISTANCE WITH
S11A1_001MH	CNL	UNABLE TO LOCATE DUE TO HEAVY VEGETATION. POSSIBLY BURIED IN WOODS.	NULL
S11A1_004MH	CNL	POSSIBLY BURIED IN WOODS. UNABLE TO LOCATE DUE TO HEAVY VEGETATION.	NULL
S11C1_012MH	CNL	(CNL) Hotel / Motel property. Can not locate.	NULL
S11E1_012MH	CNL	CNL..BURIED NOT FOUND	Not visible in the roadway according to map configuration.
S11Q_003MH	DNE	CAN NOT LOCATE - FLOATING NODE - POSSIBLE DOES NOT EXIST	CAN NOT LOCATE - FLOATING NODE - POSSIBLE DOES NOT EXIST
S11U_005MH	FINAL-CNL	FOLLOWED CREEK AND LOCATED S11U_006MH AND S11U_010MH, BUT COULD NOT FIND S11U_005MH DUE TO HEAVY VEGETATION. POSSIBLY BURIED.	NULL
S11U_013MH	FINAL-CNL	UNABLE TO LOCATE DUE TO HEAVY VEGETATION. FOLLOWED CREEK AND FOUND S11U_006MH AND S11U_010MH, BUT WAS UNABLE TO LOCATE S11U_013MH.	NULL
S11W_005MH	DNE	Cannot locate..see pics	Does not exist
S11Y_005MH	DNE	Cannot locate..see pics	Does not exist
S11Y_007MH	DNE	Cannot locate..See pics	Does not exist
S11Y_009MH	DNE	Cannot locate..see pics	Does not exist
S13S_001MH	DNE	buried or moved	Does not exist
S13S_024MH	CNL		According to master list this MH is unable to locate.
S13U_002MH	OUT OF SCOPE	Unable to locate MH, MH is either buried or doesnt exist	Unable to locate MH, MH is either buried or doesnt exist
S13U_006MH	FINAL-CNL	UNABLE TO LOCATE DUE TO HEAVY VEGETATION. MAP SHOWED MH TO BE 175FT FROM BLDG. TOOK PHOTOS OF AREA.	NULL
S13U_008MH	FINAL-CNL	ATTEMPTED TO LOCATE WITH METAL DETECTOR. DID NOT GET STRONG ENOUGH READING TO JUSTIFY DRILLING HOLE. POSSIBLY BURIED IN A PRIVATE PROPERTY PARKING LOT AREA.	NULL
S13U_010MH	OUT OF SCOPE	Unable to locate MH, MH is either buried or doesnt exist	Unable to locate MH, MH is either buried or doesnt exist
S13U_011MH	OUT OF SCOPE	Unable to inspect, because MH is buried or doesnt exist	Unable to inspect, because MH is buried or doesnt exist
S13U_012MH	OUT OF SCOPE	Unable to locate MH, MH is either buried or doesnt exist	Unable to locate MH, MH is either buried or doesnt exist
S13U_016MH	OUT OF SCOPE	Unable to locate MH, MH is either buried or doesnt exist	Unable to locate MH, MH is either buried or doesnt exist
S13U_018MH	OUT OF SCOPE	Unable to locate MH, MH is either buried or doesnt exist	Unable to locate MH, MH is either buried or doesnt exist
S15A1_009MH	FINAL-CNL	CAN NOT LOCATE - NO ACCESS HEAVY VEGETATION	NULL
S15C1_015MH	CNL	CAN NOT LOCATE	DSMH IS COVERED
S15C1_027MH	DNE		Does not exist
S15I1_013MH	CNL		Connected sewers inspected under A1629 on 09/20/2008.
S15M_017MH	CNL	DOES NOT EXIST	Unable to proceed, cannot locate manhole.
S15O_004MH	CNL	Can Not Locate	Unable to proceed, cannot locate manhole.
S15O_011MH	CNL	CAN NOT LOCATE	Connected sewers inspected under A1124 on 4/5/2008. A1156
S15O_035MH	FINAL-CNL	CAN NOT LOCATE - NO MANHOLE VISIBLE, IN CONCRETE ALLEY; UNABLE TO EFFECTIVELY USE METAL DETECTOR DUE TO PROXIMITY TO STORM GRATE	NULL
S15O_053MH	DNE	CNL	Paving where MH should be
S15Q_017MH	DNE	CAN NOT LOCATE - POSSIBLY BURIED OR DOES NOT EXIST	NULL
S15S_012MH	CNL	CAN NOT LOCATE; UNABLE TO DETERMINE WHERE TO ACCESS AREA	unable to locate US & DSMHs

S15U__002MH	DNE-Final		STORMWATER FEATURE
S15U__012MH	DNE	CNL	Paving where MH should be
S15W__003MH	FINAL-CNL	CNL - ATTEMPT TO LOCATE WITH METAL DETECTOR AND PROBE WAS UNSUCCESSFUL	NULL
S17K__019MH	DNE	CNL	only thing close is an area drain
S17K__038MH	DNE	CNL	NULL
S17M__018MH	DNE	CNL	Searched for MH in baseball field and measured from 032. MH
S17S__001MH	CNL		unable to locate US & DSMH's
S17S__002MH	CNL		unable to locate US & DSMH's
S17U__006MH	CNL	ATTEMPT TO LOCATE WAS UNSUCCESSFUL	no access / possibly abandoned
S17U__007MH	CNL	ATTEMPT TO LOCATE WAS UNSUCCESSFUL	unable to locate DSMH / USMH has no cover & is full of debris /
S17W__005MH	CNL	ATTEMPT TO LOCATE WAS UNSUCCESSFUL DUE TO HEAVY VEGETATION IN EASEMENT AND ONLY PRIVATE PROPERTY ACCESS NEAR ROADWAY	unable to locate US & DSMH's
S17W__008MH	DNE	CNL	Paving where MH should be
S17W__011MH	CNL	NEAR RAILROAD TRACKS; ATTEMPT TO LOCATE WAS UNSUCCESSFUL DUE TO SEVERAL FALSE POSSITIVE READINGS	USMH IS BURIED / UNABLE TO OPEN DSMH
S17W__014MH	CNL	ATTEMPT TO LOCATE WAS UNSUCCESSFUL DUE TO POSTED NO TRESPASSING SIGNS	unable to open USMH / unable to locate DSMH
S17Y__014MH	CNL	ATTEMPTED TO LOCATE, BUT WERE UNABLE TO ACCESS AREA	unable to locate US & DSMH's
S19A1_006MH	DNE		DNE (has been deleted from GIS)
S19G1_005MH	DNE	CNL	Paving where MH should be
S19I__015MH	CNL/DNE	STREET COVERED WITH TRASH AND DEBRIS - UNABLE TO LOCATE MANHOLE	NULL
S19K__013MH	DNE	CAN NOT LOCATE	Connected sewers inspected under A0912 on 3/18/2008.CCTV
S19M1_004MH	CNL	CNL - HOMEOWNER MOVED HIS BOAT WHICH WAS IN SUPPOSED LOCATION; USED METAL DETECTOR AND PROBE IN ATTEMPT TO LOCATE MANHOLE WITH NO SUCCESS	NULL
S19Q__005MH	DNE		NULL
S19W__021MH	DNE		DNE. According to CCTV Survey the manhole does not exist.
S21E1_025MH	DNE	CAN NOT LOCATE - FLOATING NODE, POSSIBLE DOES NOT EXIST - PAVEMENT MARKED IN SUPPOSED LOCATION	NULL
S21M__038MH	CNL		L5174. 12/19/2007. According to CCTV survey cannot locate the
S21O__001MH	DNE	ATTEMPT TO LOCATE WITH METAL DETECTOR WAS UNSUCCESSFUL - FLOATING NODE - POSSIBLE DOES NOT EXIST	NULL
S21U__001MH	FINAL-DNE		DNE
S21W__003MH	DNE	ATTEMPTED TO LOCATE BY MOVING DEBRIS WHICH WAS IN THE AREA. METAL DETECTOR INEFFECTIVE DUE TO SCRAP METAL.	DNE. A1671. 10/4/2008. According to CCTV Survey the Manhole does not exist.
S21W__004MH	DNE	ATTEMPTED TO LOCATE BEHIND FENCED AREA NEAR PROPANE TANK. METAL DETECTOR INEFFECTIVE DUE TO SCRAP METAL.	DNE. A1672. 10/4/2008. According to CCTV Survey the Manhole does not exist.
S21W__006MH	DNE	ATTEMPTED TO LOCATE BEHIND FENCED AREA NEAR PROPANE TANK. METAL DETECTOR INEFFECTIVE DUE TO SCRAP METAL.	DNE. A1672. 10/4/2008. According to CCTV Survey the Manhole does not exist.
S21W__027MH	DNE	CLEARED DEBRIS FROM AREA BUT WAS UNABLE TO LOCATE DUE TO INABILITY TO USE A METAL DETECTOR. METAL SCRAPS COVERS GROUND OF SALVAGE YARD	DNE. A1671. 10/4/2008. According to CCTV Survey the Manhole does not exist.
S23M__027MH	DNE	CAN NOT LOCATE - POSSIBLE DOES NOT EXIST - FLOATING NODE	NULL
S23Q__002MH	DNE	CNL - Inside Building	CNL - Inside Building
S23Y__004MH	CNL	CNL	According to CCTV crew, cannot locate manhole.

S23Y__009MH	CNL	CNL	According to CCTV Crew there is no access to manhole.
S23Y__010MH	CNL	CNL	According to CCTV crew, cannot locate manhole.
S23Y__011MH	CNL	CNL	According to CCTV Crew there is no access to manhole.
S23Y__014MH	CNL	CNL	According to CCTV Crew there is no access to manhole.
S23Y__015MH	CNL	CNL	According to CCTV Crew there is no access to manhole.
S23Y__025MH	CNL	CNL	NULL
S25C1__001MH	CNL	buried...see pics	According to CCTV crew, cannot locate manhole.
S25C1__G01MH	CNL	NOT FOUND; Heavy Traffic Area	NULL
S25K__027MH	CNL	mh is buried under addition to building..see pics	#NAME?
S25U__005MH	DNE	CNL	Paving where MH should be
S27I__026MH	CNL	CNL	NULL
S27K__024MH	CNL	CNL - MANHOLE ISNT UNDER TARP.	Not visible in concrete alley.
S27S__013MH	DNE	CNL	Paving where MH should be
S29E__005MH	DNE	Not found	DNE. C0142. 12/9/2008. According to the CCTV survey the
S29E__036MH	CNL	MH buried...see pics	Y1026. 2/10/2009. According to CCTV survey the manhole is a
S29E__042MH	DNE		DNE. Y1024. 2/10/2009. According to CCTV survey the manhole
S29E__064MH	CNL	Mh buried...pics taken in accordance to map	Y1025. 2/10/2009. According to CCTV survey the manhole is a
S29G__006MH	DNE	buried. Area has been reconstructed so MH is Deleted.	X0081. 2/17/2009. According to CCTV survey the manhole does not exist and it connects to a dead end.
S29G__011MH	DNE		DNE. J4027. 3/4/2009. According to CCTV survey the manhole
S29G__031MH	DNE		DNE. According to CCTV crew the manhole does not exist.
S29G__045MH	DNE	CNL	sidewalk & grating where MH should be
S29G__057MH	CNL	CNL. RENOVATION OF AREA MH NOT FOUND OR INSIDE HOUSE	NULL
S29G__068MH	CNL	not found	According to Survey Crew there is no access to this manhole.
S29I__002MH	CNL	CNL:BURIED	NULL
S29I__004MH	CNL	CNL-BUILDING	NULL
S29I__011MH	CNL	CNL-building	M0147. 11/17/2008. According to survey there is no access to
S29I__018MH	CNL	CNL see pics...	NULL
S29K__030MH	CNL	Buried in carport.	Buried in carport.
S29K__039MH	DNE	Unable to locate MH, MH is either buried or doesnt exist	According to Survey Crew the manhole does not exist.
S29K__049MH	CNL	Unable to locate MH, MH is either buried or doesnt exist	In the backyard of 1056 W.Barre St.
S29K__060MH	CNL	MH is Buried, in court yard of back yard cement	MH is Buried, in court yard of back yard cement
S29K__071MH	DNE	Unable to locate MH, MH is either buried or doesnt exist	According to the CCTV survey crew the manhole does not exist.
S29K__079MH	CNL	MH is buried near garage and front of cement carport	MH is buried near garage and front of cement carport
S29M__034MH	DNE	CNL	DNE. According to the CCTV Survey crew tha manhole does not
S29M__044MH	CNL	CNL-UNABLE TO CONFIRM OR DENY PRESENCE OF STRUCTURE IS NOT VISIBLE ABOVE GROUND	NULL
S29M__060MH	DNE	Buried not in parking lot, need to dig up	DNE. According to CCTV Survey the manhole does not exist.
S29O__009MH	DNE	See pics... Record exists-Image file not available- all images missing	K0852. 5/21/2008. According to the CCTV survey the manhole does not exist.
S29O__010MH	DNE	Record exists-Image file not available- all images missing Buried...see pics	C0363. 3/17/2009. According to the CCTV survey the manhole does not exist.
S29O__041MH	DNE	See pics...	DNE. C0361. 3/17/2009. According to CCTV survey the manhole
S29O__046MH	DNE	Buried...see pics	DNE. C0360. 3/17/2009. According to CCTV survey the manhole
S29O__054MH	CNL	Buried...see pics	Buried...see pics
S29Q__023MH	DNE	buried or moved	K0857. 5/22/2008. According to CCTV survey the manhole does
S29S__007MH	DNE	Couldnt locate, MH is buried	DNE (has been deleted from GIS per dwgs)
S29Y__001MH	CNL	NSA-BUILDING	NULL
S31G__016MH	DNE	Not Found	C0285. 2/12/2009. According to CCTV survey the manhole does
S31G__035MH	DNE	Not there	C0178. 12/15/2008. According to CCTV survey the manhole does
S31G__038MH	CNL	not found	NULL
S31I__014MH	CNL	construction area, alley is gone and so are the manholes	ATS CHESTER--construction area, alley is gone and so are the manholes
S31I__023MH	DNE	NOT THERE	According to CCTV Survey crew the manhole is does not exist.
S31I__024MH	CNL	Unable to locate, due to construction being done in area	#NAME?

S31I__035MH	CNL	not there	ATS CHESTER--not there
S31I__A01MH	CNL		NULL
S31O__002MH	CNL	Unable to locate MH, believed to be buried in parking lot	Unable to locate MH, believed to be buried in parking lot
S31Q__002MH	DNE	CNL	Grassy area- dug around some, no MH
S31Q__009MH	DNE	CNL	Gravel & tracks where MH should be
S31Q__035MH	CNL	Manhole does not exist. Was replaced during stadium construction.	Manhole does not exist. Was replaced during stadium construction.
S31S__002MH	DNE	CNL	Actual utility configuration in this area does not match maps at
S31S__003MH	CNL	not there	According to the CCTV survey crew cannot locate manhole.
S31S__007MH	DNE	CNL	Grassy area where MH should be
S33C__019MH	CNL	not there	ATS CHESTER--not there
S33G__020MH	CNL	not there	NULL
S33G__025MH	CNL	not there	NULL
S33G__026MH	CNL	Not Found	C0347/ C0348. 3/15/2009. According to the CCTV survey the
S33I__008MH	DNE	Not there	Sewer segment is under new development. It is abandoned or DNE. 02/16/2009.C0305/C0304. CCTV by Hydromax. Manhole
S33I__032MH	CNL	not found	ATS CHESTER--not found
S33K__001MH	CNL	not found	02/16/2009.C0300. CCTV by Hydromax. Can not locate manhole S33K__001MH. 8" Sewer segment is abandoned. MH abd,
S33K__003MH	CNL	not found	02/16/2009.C0300. CCTV by Hydromax. Can not locate manhole S33K__003MH. 8" Sewer segment is abandoned. MH abd,
S33K__004MH	DNE	not found	02/16/2009.C0301/C0302. CCTV by Hydromax. Manhole S33K__004MH does not exist or covered. Sewer segment is
S33K__019MH	CNL	not found	02/16/2009.C0301/C0302/C0303. CCTV by Hydromax. Manhole S33K__019MH does not exist or covered. Sewer segment is
S33K__021MH	DNE	CNL	Paving where MH should be
S33M__006MH	DNE	CNL	Paving where MH should be
S33M__020MH	DNE	CNL	sidewalk & tree where MH should be
S33O__054MH	DNE	CNL	Paving where MH should be
S33Q__030MH	CNL	not found	03/28/2008.K0602/K0603. CCTV was done by REI Drayco. Manhole S33Q__030MH has no riser and has been bricked off
S33Q__045MH	CNL	Not there	ATS CHESTER--Not there
S33Q__049MH	CNL	not found	02/25/2009. J6140. CCTV was done by REI Drayco. Manhole S33Q__049MH is a Domestic Sewer connection to interceptor. It
S33S__017MH	CNL	not found	not found
S33S__024MH	CNL	not found	not found
S33U__014MH	CNL	not found	not found
S33W__003MH	DNE	CNL...see pics	Paving where MH should be, possible cleanout
S33W__004MH	CNL	NOT THERE	NOT THERE
S33W__009MH	CNL	not found	not found
S35A__005MH	CNL	not there	not there
S35A__026MH	DNE	CNL...in building...see pics	No MH seen inside building
S35A1_001MH	CNL	not found	not found
S35A1_006MH	CNL	not found	not found
S35C__007MH	CNL		
S35C__009MH	CNL	not found	NULL
S35C__012MH	CNL		#NAME?
S35C__061MH	CNL	not found	not found
S35CC_035MH	CNL	whole not found info is for 012	NULL
S35E__007MH	CNL	not there	NULL
S35E__012MH	CNL	street is gone	NULL
S35E__045MH	CNL	not found	NULL
S35E__052MH	CNL	not found	NULL
S35E__054MH	CNL	no access...area under construction	NULL
S35E__057MH	CNL	not found	NULL
S35G__004MH	DNE	CNL ...see pics	Paving where MH should be
S35G__019MH	DNE	CNL...see pics	Paving where MH should be
S35G__034MH	CNL	not found	NULL
S35G__045MH	DNE	not found	11/13/2008.C0011 CCTV was done by Hydromax. Manhole
S35G__046MH	CNL	CNL...see pics	Actual utility configuration in this intersection does not match
S35G__050MH	DNE	CNL...see pics	Paving where MH should be
S35G__057MH	CNL		
S35G__062MH	CNL	not found	4/29/09. S5052/S5053. LL-S029. CCTV was done by VPS. Unable to proceed due to a collapsed pipe. CNL S35G__062MH.

S35G__069MH	DNE	not found	05/04/2009. 1095/1096. CCTV was attempted by VPS. Manhole
S35I__011MH	DNE	CNL...see pics	Paving where MH should be
S35I__029MH	DNE	CNL....see pics	Plants & sidewalk where MH should be
S35M__022MH	CNL	Not There	NULL
S35M__033MH	DNE	CNL....see pics	brick pavers & sidewalk where MH should be
S35M__041MH	DNE	CNL...see pics	Paving where MH should be
S35O__006MH	CNL	not found	NULL
S35O__039MH	DNE	not found	02/2008.K0408. CCTV was done by REI Drayco. Manhole S35O__039MH does not exist. Sewer segment is from
S35O__052MH	CNL	not found	CCTV inspection is not done.
S35Q__044MH	DNE	CNL...see pics	concrete pad where MH should be
S35Q__046MH	CNL	not found	02/05/2008.K0369. CCTV was done by REI Drayco. Manhole
S35Q__065MH	CNL	not found	NULL
S35S__022MH	DNE	CNL...see pics	Paving where MH should be
S35S__031MH	CNL	not found	03/25/2009. J6239. CCTV was done by REI Drayco. Manhole
S35S__032MH	CNL		#NAME?
S35S__045MH	DNE	CNL...see pics	Paving where MH should be
S35U__003MH	DNE	CNL....see pics	Paving where MH should be
S35U__019MH	DNE	CNL...see pics	Paving where MH should be
S35U__025MH	DNE	CNL...see pics	Paving where MH should be
S35U__034MH	CNL	not found	NULL
S35U__036MH	CNL	not found	NOT FOUND
S35W__029MH	CNL	not found	NULL
S35W__045MH	DNE	CNL...see pics	Sidewalk & paving where MH should be
S35Y__002MH	DNE	CNL...see pics	Paving where MH should be
S37A__001MH	OUT OF SCOPE	not found	03/31/09. N0997. CCTV was attempted by VPS. Can Not Locate S37A__001MH. 6" Pipe: don't need to inspect this manhole.
S37AA_019MH	DNE	CNL...see pics	Paving where MH should be
S37AA_021MH	CNL	not found	NULL
S37AA_028MH	CNL	not found	NULL
S37AA_035MH	CNL	not found	not found
S37C__005MH	CNL	Manhole & High St Gone	Manhole & High St Gone
S37C__025MH	CNL	Manhole & Street gone	Manhole & Street gone
S37C__046MH	DNE	CNL....see pics	New sidewalk & pavers where MH should be
S37CC_020MH	DNE	CNL...see pics	Grassy area where MH should be
S37CC_053MH	DNE	CNL....see pics	Paving where MH should be
S37CC_060MH	CNL	Not There	Not There
S37E__016MH	CNL	Not there	Not found
S37E__020MH	DNE		Paving where MH should be
S37E__022MH	CNL	Not there	NULL
S37E__026MH	DNE	CNL...see pics	brick paving and courtyard where MH should be
S37E__029MH	CNL	not found	NULL
S37E__036MH	DNE	CNL...see pics	Paving where MH should be
S37G__014MH	CNL	Not found	Not found
S37G__047MH	CNL	NOT FOUND	NOT FOUND
S37G__052MH	CNL	under building	under building
S37I__039MH	CNL	not found	02/16/2009.N0726. CCTV was done by VPS. Manhole
S37M__003MH	CNL	Not there	Not there
S37O__001MH	DNE	CNL...see pics	Paving where MH should be
S37O__011MH	CNL	not found	NULL
S37O__016MH	DNE	CNL....see pics	Mulch & planting bed where MH should be
S37O__030MH	DNE	CNL...see pics	
S37O__031MH	DNE	CNL...see pics	Grassy area where MH should be
S37O__035MH	CNL	not found	NULL
S37O__040MH	CNL	Not found	Not found
S37Q__009MH	DNE	CNL...see pics	grass & paving where MH should be
S37Q__017MH	DNE	CNL...see pics	Paving where MH should be
S37Q__020MH	CNL	not found	NULL
S37Q__021MH	OUT OF SCOPE	Not Found	03/10/2009. J6178. LL-J015. CCTV was done by REI Drayco. Unable to proceed due to change of Pipe Dia from 8" to 6"
S37Q__044MH	DNE	CNL...see pics	Paving where MH should be
S37S__022MH	CNL	not found	NULL
S37S__048MH	CNL	not found	NULL
S37S__057MH	CNL	not found	NULL
S37U__006MH	CNL	not found	NULL

S37U__027MH	DNE	CNL...see pics	Paving where MH should be
S37U__036MH	CNL	not found	NULL
S39A__012MH	CNL	not found	NULL
S39A__015MH	DNE	CNL....see pics	Fountain & garbage where MH should be
S39A__030MH	CNL	not found	NULL
S39A__032MH	DNE	CNL... Inside buliding...See pics	Locked, Abandoned buildings where MH should be
S39A__060MH	CNL		ATS CHESTER-SCOM-Not there no more, so cant take pictures of
S39AA_008MH	CNL	under building	under building
S39AA_025MH	CNL	not found	NULL
S39AA_029MH	CNL	under building	under building
S39AA_040MH	DNE	not found	10/30/2008. N0288. LL-N025. CCTV was done by VPS. Manhole S39AA_040MH does not exist. Sewer segment is from
S39C__016MH	CNL	mh not found	ATS CHESTER-NA-mh not found
S39CC_001MH	CNL	not found	not found
S39CC_026MH	CNL	Unable to Locate	#NAME?
S39E__001MH	CNL	not found	not found
S39E__004MH	CNL	NOT FOUND	NULL
S39E__005MH	CNL	NOT FOUND	NULL
S39E__010MH	CNL	not found	ATS CHESTER-SCOM-not found
S39G__005MH	DNE	not found	03/26/2009.C0400; LL-C025. CCTV was done by Hydromax.
S39G__018MH	CNL	under building	under building
S39G__029MH	CNL		
S39G__041MH	CNL	not found	NULL
S39I__009MH	CNL	Not found	Not found
S39I__015MH	DNE	CNL	Paving & sidewalk where mH should be
S39I__031MH	CNL	Not Found	Not Found
S39I__037MH	CNL	Not found	Not found
S39I__050MH	CNL	not found	NULL
S39K__017MH	DNE	CNL	mulch bed & landscaping where MH should be
S39K__018MH	CNL	not found	NULL
S39K__019MH	CNL	not found	NULL
S39K__029MH	CNL	not found	not found
S39K__038MH	CNL	not found	NULL
S39Q__002MH	CNL	not found	not found
S39Q__004MH	CNL	not found	not found
S39Q__005MH	CNL	not found	not found
S39Q__008MH	CNL	not found	NULL
S39S__014MH	DNE	CNL...see pics	sidewalk where MH should be
S39S__041MH	DNE	CNL...see pics	Tree & flower bed where MH should be
S39U__015MH	CNL	Not there	NULL
S39U__031MH	CNL	not found	NULL
S39Y__010MH	DNE	CNL...see pics	Sidewalk & compacted dirt where MH should be
S41A__006MH	CNL	not found	NULL
S41A__008MH	CNL	not found	not found
S41A__012MH	CNL	not found	not found
S41A__015MH	CNL	not there	ATS CHESTER-NA-not there
S41A__032MH	CNL	not found	NULL
S41A__033MH	DNE		Major construction & site grading where MH should be
S41A__038MH	CNL	not found	not found
S41AA_027MH	CNL	not found	NULL
S41AA_030MH	CNL	not found	NULL
S41AA_048MH	CNL	not found	Unable to proceed, no access/cannot locate MH. Master List 3D shows attempted on 3/27/2009 under N0975/N0976 (reverse).
S41AA_054MH	CNL	not found	MH does not connect to sewer system, according to GIS, and is close to S41AA_009MH, which has been surveyed and
S41AA_077MH	CNL	not there	ATS CHESTER-SCOM-not there
S41AA_095MH	DNE	under building	Attempted on 4/28/2009 under S5046. DNE.
S41C__002MH	CNL	Not found	Unable to proceed, cannot locate manhole.
S41C__016MH	CNL	Not found	NULL
S41C__026MH	CNL	Not found	Unable to proceed cannot locate manhole. K1247 (9/12/2008).
S41C__034MH	CNL	Not found	Unable to proceed, cannot locate manhole.
S41C__048MH	CNL	not found	NULL
S41C__049MH	CNL	Not Found	K1246 (9/12/2008). LL-K074. REI. Unable to proceed due to
S41C__058MH	CNL	Not Found	Unable to proceed, cannot locate manhole.
S41CC_004MH	DNE	under building	DNE

S41CC_012MH	DNE	Inside private residence...see pics	Building where MH should be
S41CC_018MH	DNE	under builing	DNE
S41CC_027MH	CNL	Not Found	Unable to proceed, cannot locate manhole.
S41CC_036MH	CNL	Not Found	Unable to proceed, cannot locate manhole.
S41CC_049MH	DNE	not found	Attempted on 3/19/2009 under N0886. DNE.
S41CC_051MH	CNL	not found	N0197 (10/8/2008). LL-N016. Unable to proceed due to
S41CC_055MH	DNE	Inside private residence...see pics	Building where MH should be
S41CC_065MH	CNL	not found	Unable to proceed, cannot locate manhole.
S41E_013MH	CNL	not found	Unable to proceed, no access (within a building).
S41E_038MH	CNL	not found	not found
S41E_039MH	CNL	not found	Unable to proceed, no access (within a building).
S41E_046MH	CNL	not found	Unable to proceed, no access (within a building).
S41E_058MH	CNL	not there	NULL
S41E_074MH	CNL	not found	Unable to proceed, no access (within a building).
S41G_026MH	CNL	not there	ATS CHESTER-NA-not there
S41I_012MH	DNE	CNL...inside parking got garage...see pics	Parking garage & paving where mH should be
S41I_017MH	CNL	not there	ATS CHESTER--not there
S41I_031MH	DNE	CNL...see pics	Paving where MH should be
S41I_040MH	CNL	not there	ATS CHESTER--not there
S41I_060MH	DNE	CNL.... see pics	sidewalk where MH should be
S41I_066MH	CNL	Not Found	NULL
S41M_010MH	CNL	Not Found	Unable to proceed, no access; Unable to proceed due to
S41W_022MH	CNL	CNL...see pics	CNL in baseball field. Could not confirm or deny existence
S41W_027MH	CNL	CNL...see pics	Actual utility configuration in this area does not match maps
S41Y_003MH	CNL	not found	Unable to Survey due to high water level. T0345. LL-T027. Savin. Survey not found in supplemental database, but is shown
S41Y_004MH	CNL	not found	Unable to Survey due to high water level. T0345. LL-T027. Savin. Survey not found in supplemental database, but is shown
S41Y_006MH	CNL	not found	not found
S43AA_018MH	CNL	not found	NULL
S43CC_027MH	DNE	not found	Attempted on 3/17/2009 under N0827/N0828 (reverse)/N0825.
S43CC_034MH	CNL	not found	Attempted on 2/9/2009 under N0703/N0704 (reverse). Unable
S43CC_044MH	CNL	constrution zone possibly not there	ATS CHESTER-SCOM-constrution zone possibly not there
S43CC_051MH	CNL	constrution zone possibly not there	ATS CHESTER--constrution zone possibly not there
S43CC_052MH	CNL	First done on 12/19/07 & Still not there on 6/17/08	ATS CHESTER-SCOM-First done on 12/19/07 & Still not there on 6/17/08
S43CC_059MH	CNL	not found	not found
S43CC_069MH	CNL	constrution zone possibly not there	ATS CHESTER--constrution zone possibly not there
S43E_004MH	CNL	not found	Complete on 3/23/2009 under T0492. S43E_004MH shown as S43E_004DE in survey since the line is end of pipe.
S43E_014MH	DNE	CNL...see pics	grass where MH should be
S43E_050MH	FINAL-CNL	07/29/2009 11:32 AM LOCATED WITH METAL DETECTOR AND MARKED PAVEMENT; UNABLE TO EXPOSE DUE TO PAVING; 07/30/2009 08:28 AM EXCAVATED 2 BELOW INDICATED LOCATION ONLY TO FIND PIECES OF SCRAP METAL - NO MANHOLE LOCATED	NULL
S43E_075MH	CNL	not there	not there
S43G_002MH	DNE	CNL...see pics	Paving where MH should be
S43G_004MH	DNE	not found	Complete on 1/23/2009 under K1470. Surveys S43E_031MH to
S43G_013MH	CNL	not there	Complete on 3/25/2009 under T0509. S43G_013MH shown as
S43G_024MH	CNL	not found its abandoned at the basketball courts of school	ATS CHESTER-SCOM-not found its abandoned at the basketball courts of school
S43G_034MH	FINAL-CNL	NO ACCESS - INSIDE SCHOOL BUILDING	NULL
S43G_044MH	CNL	under apt.	ATS CHESTER--under apt.
S43I_026MH	CNL	not found	Complete on 10/20/2008 under L5517.
S43I_037MH	DNE	CNL...see pics	Paving where MH should be
S43K_001MH	CNL	not found	K1389 (11/24/2008). LL-K084. Unable to pass compact deposits. About 284 ft remaining. Cannot locate
S43S_001MH	CNL	not found	not found
S43S_012MH	CNL	not found	not found
S45CC_005MH	CNL	construction zone possibly not there	ATS CHESTER-SCOM-construction zone possibly not there
S45CC_009MH	CNL	constrution zone possibly not there	ATS CHESTER-SCOM-constrution zone possibly not there
S45CC_038MH	CNL	constrution zone possibly not there	ATS CHESTER-SCOM-constrution zone possibly not there

S45CC_043MH	CNL	construction zone possibly not there	ATS CHESTER-SCOM-construction zone possibly not there
S45CC_052MH	DNE	not found	Complete on 8/29/2008 under N0011. Survey shows from
S45E_050MH	CNL	not found	NULL
S45EE_011MH	CNL	not found	NULL
S45EE_017MH	DNE	not found	Have no access because of fenced construction area. Master List 3D also shows attempted on 2/5/2009 under N0680. DNE.
S45G_003MH	CNL	not found	Complete on 4/7/2009 under N1048/N1049 (separate). Both
S45G_009MH	CNL	not found	Complete on 4/7/2009 under N1053/N1054 (separate). Both
S45I_008MH	DNE	CNL....see pics	Paving and concrete gutter where MH should be
S45I_044MH	DNE	CNL...see pics	Paving where MH should be
S45K_002MH	DNE	CNL...see pics	Paving where MH should be
S45K_043MH	CNL	not found	Y0953 (11/5/2008). LL-Y051. Unable to pass heavy material. About 51 ft remaining. Master List 4 also shows attempted on
S45Y_004MH	DNE	NOT THERE	Attempted on 2/24/2009 under T0339. DNE.
S45Y_009MH	DNE	CNL	Parking garage & paving where mH should be
S47A1_001MH	CNL	NOT FOUND	NULL
S47I_021MH	DNE	not found	Attempted on 10/1//2008 under Y0808. S47I_021MH DNE.
S47I_023MH	DNE		Paving where MH should be
S47I_034MH	CNL	not found	ATS CHESTER-NA-not found
S47I_040MH	CNL	not found	ATS CHESTER-NA-not found
S47I_045MH	CNL	not found	ATS CHESTER-NA-not found
S47M_002MH	DNE	CNL...see pics	Paving where MH should be
S49A_038MH	DNE		DOES NOT EXIST; ONLY 1 SEWER FEATURE WHICH IS
S49A_057MH	CNL	not there	T0112 (12/22/2008). LL-T017. Unable to proceed due to high water level. About 100 ft remaining. T0113 (12/22/2008). LL-T017. Unable to proceed due to high water level. Both surveys
S49E_014MH	OUT OF SCOPE	not found	NULL
S49G_004MH	CNL	not found	NULL
S49M_006MH	CNL	not there	T0019 (12/1/2008). LL-T012. Unable to proceed due to high water level. Master List 5 also shows attempted (no survey) and
S49M_032MH	CNL	Not found	Complete on 9/24/2008 under W0353. Survey found MH as DE.
S49M_041MH	DNE	not there	Complete on 10/1/2008 under W0395. Surveys S49M_018MH to S49M_004MH without noting about S49M_041MH. MH not on sanitary sewer, according to redline
S49M_042MH	CNL	not found	NULL
S49M_045MH	CNL	not found	W0399 (10/2/2008). LL-W015. Unable to proceed due to deposits attached to the surface. About 14 ft remaining. MH is
S51A_036MH	CNL	not found	T0109 (12/21/2008). LL-T017. Unable to proceed due to high water level. About 32 ft remaining. MH no longer exists,
S51AA_017MH	CNL	not found	NULL
S51AA_032MH	CNL	not found	NULL
S51E_005MH	CNL	not found	NULL
S51E_024MH	CNL	not found	NULL
S51E_027MH	CNL	not found	ATS CHESTER--not found
S51G_003MH	DNE	not found	DNE
S51K_003MH	DNE	not found	Not done, 033 & 003 are buried or DNE and JOM stops CCTV
S51K_033MH	DNE	not found	Not done, 033 & 003 are buried or DNE and JOM stops CCTV from downstream. X0064 (11/21/2008) LL-X005. Unable to
S51O_006MH	CNL final	CNL - IN LANDSCAPED AREA OR UNDER PAVEMENT, METAL DETECTOR PICKING UP NEAR BY OBJECTS AND IS INEFFECTIVE (see photo for supposed location)	NULL
S51O_046MH	DNE	not found	Attempted on 1/21/2009 under T0240. DNE.
S51O_047MH	CNL	not found	T0147 (1/7/2009). LL-T019. Unable to proceed due to bend in
S51O_049MH	DNE	not found	Attempted on 1/21/2009 under T0239/T0243 (separate). DNE.
S51O_056MH	DNE	not found	Attempted on 1/21/2009 under T0240/T0244 (separate). DNE.
S51O_058MH	DNE	CNL...see pics	grass & sidewalk where MH should be
S53C_053MH	DNE	CNL....see pics	Paving where MH should be
S53E_031MH	DNE	CNL...see pics	Paving/concrete alleyway where mH should be
S53O_032MH	CNL	not there	Complete on 8/14/2008 under W0106. Survey shows MH as DE.
S53Q_009MH	DNE	not found	DNE
S55C_024MH	DNE	CNL...see pics	Paving where MH should be
S55C1_007MH	CNL	not found	NULL
S55C1_008MH	CNL	not found	NULL
S55I_007MH	DNE	CNL...see pics	Paving where MH should be

S55K__051MH	CNL	not found	NULL
S55O__028MH	CNL	under building	under building
S55O__042MH	CNL	under building	under building
S55S__007MH	CNL	CNL...see pics	NULL
S57C1_002MH	DNE	not found	DNE
S57S__011MH	DNE	not found	DNE
S59A__001MH	FINAL-CNL	CAN NOT LOCATE - SUPPOSED LOCATION MARKED WITH CONE IN PHOTO	NULL
S61M__004MH	DNE	not there	Attempted on 1/22/2009 under Y0979/Y0980 (separate). DNE.